

WEST Search History

DATE: Wednesday, August 04, 2004

Hide?	<u>Set</u> <u>Name</u>	<u>Query</u>	<u>Hit</u> <u>Count</u>
	<i>DB=PGPB,USPT,USOC,EPAB,JPAB,DWPI; PLUR=YES; OP=OR</i>		
<input type="checkbox"/>	L28	l2 and temper\$3 and hardening and (warm near forg\$3)	1
<input type="checkbox"/>	L27	l2 and temper\$3 and hardening	66
<input type="checkbox"/>	L26	l2 and 148/663.ccls.	8
<input type="checkbox"/>	L25	l2 and 148/649.ccls.	2
<input type="checkbox"/>	L24	4115111	18
<input type="checkbox"/>	L23	4871268	17
<input type="checkbox"/>	L22	L16 and 384/912.ccls.	14
<input type="checkbox"/>	L21	L16 and 384/625.ccls.	4
<input type="checkbox"/>	L20	L16 and 148/906.ccls.	12
<input type="checkbox"/>	L19	L16 and 148/335.ccls.	19
<input type="checkbox"/>	L18	L16 and 420/109.ccls.	12
<input type="checkbox"/>	L17	L16 and 420/108.ccls.	14
<input type="checkbox"/>	L16	L15 and hardness	914
<input type="checkbox"/>	L15	L1 and (bearing or roller or race)	1942
<input type="checkbox"/>	L14	L10 and 384/625.ccls.	3
<input type="checkbox"/>	L13	L10 and 384/912.ccls.	7
<input type="checkbox"/>	L12	L10 and 148/906.ccls.	8
<input type="checkbox"/>	L11	L10 and 148/335.ccls.	8
<input type="checkbox"/>	L10	l1 and (surface near hardness)	287
<input type="checkbox"/>	L9	l2 and 384/912.ccls.	1
<input type="checkbox"/>	L8	l2 and 384/625.ccls.	0
<input type="checkbox"/>	L7	l2 and 148/906.ccls.	2
<input type="checkbox"/>	L6	l2 and 148/335.ccls.	17
<input type="checkbox"/>	L5	l4 and (surface near hardness)	19
<input type="checkbox"/>	L4	L3 and surface	58
<input type="checkbox"/>	L3	L2 and hardness	82
<input type="checkbox"/>	L2	L1 and forg\$3 and normaliz\$6	129
<input type="checkbox"/>	L1	steel and carbon and silicon and manganese and chromium and molybdenum and nickel and iron	9107

END OF SEARCH HISTORY

WEST Search History

DATE: Wednesday, August 04, 2004

Hide?	<u>Set</u> <u>Name</u>	<u>Query</u>	<u>Hit</u> <u>Count</u>
	<i>DB=PGPB,USPT,USOC,EPAB,JPAB,DWPI; PLUR=YES; OP=OR</i>		
<input type="checkbox"/>	L36	L34 and normaliz\$6	44
<input type="checkbox"/>	L35	L34 and (induction near hardening)	4
<input type="checkbox"/>	L34	L33 and hardening and temper\$3	224
<input type="checkbox"/>	L33	L1 and bearing	1425
<input type="checkbox"/>	L32	l31 and (induction near harden\$3)	1
<input type="checkbox"/>	L31	L29 and temper\$3 and hardness	43
<input type="checkbox"/>	L30	L29 and quench\$3 and temper\$3	34
<input type="checkbox"/>	L29	L1 and race	100
<input type="checkbox"/>	L28	l2 and temper\$3 and hardening and (warm near forg\$3)	1
<input type="checkbox"/>	L27	l2 and temper\$3 and hardening	66
<input type="checkbox"/>	L26	l2 and 148/663.ccls.	8
<input type="checkbox"/>	L25	l2 and 148/649.ccls.	2
<input type="checkbox"/>	L24	4115111	18
<input type="checkbox"/>	L23	4871268	17
<input type="checkbox"/>	L22	L16 and 384/912.ccls.	14
<input type="checkbox"/>	L21	L16 and 384/625.ccls.	4
<input type="checkbox"/>	L20	L16 and 148/906.ccls.	12
<input type="checkbox"/>	L19	L16 and 148/335.ccls.	19
<input type="checkbox"/>	L18	L16 and 420/109.ccls.	12
<input type="checkbox"/>	L17	L16 and 420/108.ccls.	14
<input type="checkbox"/>	L16	L15 and hardness	914
<input type="checkbox"/>	L15	L1 and (bearing or roller or race)	1942
<input type="checkbox"/>	L14	L10 and 384/625.ccls.	3
<input type="checkbox"/>	L13	L10 and 384/912.ccls.	7
<input type="checkbox"/>	L12	L10 and 148/906.ccls.	8
<input type="checkbox"/>	L11	L10 and 148/335.ccls.	8
<input type="checkbox"/>	L10	l1 and (surface near hardness)	287
<input type="checkbox"/>	L9	l2 and 384/912.ccls.	1
<input type="checkbox"/>	L8	l2 and 384/625.ccls.	0
<input type="checkbox"/>	L7	l2 and 148/906.ccls.	2

<input type="checkbox"/>	L6	12 and 148/335.ccls.	17
<input type="checkbox"/>	L5	14 and (surface near hardness)	19
<input type="checkbox"/>	L4	L3 and surface	58
<input type="checkbox"/>	L3	L2 and hardness	82
<input type="checkbox"/>	L2	L1 and forg\$3 and normaliz\$6	129
<input type="checkbox"/>	L1	steel and carbon and silicon and manganese and chromium and molybdenum and nickel and iron	9107

END OF SEARCH HISTORY